



West view, north side of middle area of 285th Street West



East view, western area of 285th Street West



Cleaned and reshaped ditch. North side of 285th Street West



Frost boil repairs. East side, middle area of Jamaica Avenue



Frost boil repairs. Mid-section, Jamaica Avenue.



Frost boil repairs on Jamaica Avenue.



Frost boil repairs. South of Town Hall on Guam Avenue.



Repairing frost boils. South end of Guam Avenue.



Repairing frost boils south of Town Hall on Guam Avenue.



Preparing for paving project on Dresden Avenue.



Repairing cracks and “tight grading” Dresden Avenue before paving.



Paving south end of Dresden Avenue.



East side of north end of Dresden Avenue during paving.



North end of Dresden Avenue during paving.



South view of Dresden Avenue after paving and striping.



North view of Dresden Avenue after paving and striping.



South end of Dunbar Avenue before ditch reshaping.



Northwest curve of Drexel and Dunbar Avenue before improvement work.



South end of Dunbar Avenue during improvement work.



North end of Drexel Avenue, west side, during improvement work.



West view, Drexel & Dunbar Avenue curve.



South end of Dunbar Avenue, after improvement work.



North end of Drexel Avenue, after improvement work.



West side of north end of Drexel Avenue after ditch reshaping.



New Dutch Creek bridge construction on County #90, 300th, Street West.



North west view, 300th Street West, during bridge construction.



Erosion control work on bridge site on Dakota County #90.



The finished bridge on Dakota County #90, 300th, Street West,
This project was designed and funded by Dakota County